IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 6,904,013

USPTO CONFIRMATION CODE: 4466

APPLICATION NO.: 09/778,101

FILED: February 07, 2001

EXAMINER: Brian Nguyen

GROUP ART UNIT: 2661

FOR: ERROR HANDLING WITHIN POWER AMPLIFIER MODULES IN

WIRELESS BASE-STATION

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION FOR USPTO MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 09/778,101, now Patent Number 6,904,013.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

All errors were the fault of the USPTO, no fee required. In the event that a further fee is required, please charge the amount to our Deposit Account No. 50-1379.

The exact locations where the errors appear in the patent and patent application are as follows:

In Column 4, Line 63, delete "0" and insert - - 10 - -, therefor. (ORIGINALLY FILED SPECIFICATION DATED FEBRUARY 7, 2001, PAGE 7, LINE 20)

In Column 8, Line 49, in Claim 1, delete "end" and insert - - and - -, therefor. (AMENDMENTS TO THE CLAIMS, DATED OCTOBER 6, 2004, PAGE 3 OF 7, CLAIM 1, LINE 5)

In Column 9, Line 6, in Claim 1, after "group" insert - - of - -. (AMENDMENTS TO THE CLAIMS, DATED OCTOBER 6, 2004, PAGE 3 OF 7, CLAIM 1, LINE 20)

In Column 9, Line 20, in Claim 3, delete "such" and insert - - each - -, therefor. (ORIGINALLY FILED SPECIFICATION IN THE CLAIMS, DATED FEBRUARY 7, 2001, PAGE 15, CLAIM 4, LINE 3)

In Column 10, Line 3, in Claim 4, after "a" insert - - fault - -, therefor. (AMENDMENTS TO THE CLAIMS, DATED OCTOBER 6, 2004, PAGE 4 OF 7, CLAIM 5, LINE 10)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

Aug. 30, 2007 /SIDNEY L. WEATHERFORD, Rea #45602/

DATE Sidney L. Weatherford

Registration No. 45602

Attorney of Record

Page 1 of 1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,904,013 B2

APPLICATION NO.: 09/778,101

ISSUE DATE

: June 7, 2005

INVENTOR(S)

: Goran Skoog, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 4, Line 63, delete "0" and insert - - 10 - -, therefor.

In Column 8, Line 49. in Claim 1, delete "end" and insert - - and - -, therefor.

In Column 9, Line 6, in Claim 1, after "group" insert - - of - -.

In Column 9, Line 20, in Claim 3, delete "such" and insert - - each - -, therefor.

In Column 10, Line 3. in Claim 4, after "a" insert - - fault - -, therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

6300 Legacy, MS EVR 1-C-11 Plano, TX 75024 972-583-8656

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.